

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937
UNKNOWN
N

BAKER R. 1V/3H
1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Alkalinity (mg/L) | Bromide (mg/L) | Chloride (mg/L) |
|--------------------------------------|---|---|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|-------------------|----------------|-----------------|
| Primary Maximum Contaminant Levels | a | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | b | | | | | | | | | | 250 |
| Recommended Action Levels | | c | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | 21.9 |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | 18.4 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | 10.4 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | 12 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | 9.39 |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | | 14.2 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | 5.55 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | 15 |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | 13.8 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | 32.2 |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | 33.4 |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | 96 | NON DETECT | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | 86.6 | | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | 91.6 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | 92.8 | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | <94.1 | | <43.7 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | 90.2 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | 85.2 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | 83.8 | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Chloride (SAC 942) (mg/L) | Conductivity (us/cm) | DO (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|---------------------------|----------------------|-----------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | 250 | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | 2.62 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | 2.6 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | 3.01 |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | 1.88 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | 269 | 3.28 |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | 268 | 5.96 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | 355 | 5.54 |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | 364 | 6.05 |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | 47.7 | 336 | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | 7.13 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | 45.1 | 343 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | 45.2 | 338 | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | 51.5 | 353 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | 55.6 | 361 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | 56.1 | 365 | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Hardness (mg/L) | MBAS (mg/L) | ORP (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|-----------------|-------------|------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | 0.5 | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | <0.2 | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | <0.02 | 177 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | <0.02 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | <0.08 | 71.1 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | <.08 | 161.6 |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | <0.100 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | <0.1 | 84.2 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | <0.080 | 84.800 mV |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | <0.080 | 69.400 mV |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | <0.080 | 192.000 mV |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | <0.080 | 194.500 mV |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | 126 | | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | 189.6 mV |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | 135 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | 134 | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | | <0.025 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | 144 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | 136 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | 136 | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | pH (pH units) | Sulfate (mg/L) | Sulfide (mg/L) |
|--------------------------------------|---|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|---------------|----------------|----------------|
| Primary Maximum Contaminant Levels | a | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | b | | | | | | | | | 6.5-8.5 | 250 | |
| Recommended Action Levels | c | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | 7.61 | | <1 |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | 7.7 | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | 7.5 | | <1 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | 7.8 | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | 7.63 | | <1 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | 7.68 | | <1 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | 8 | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | 7.81 | | <1 |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | 7.67 | | <1.000 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | 7.86 | | <1 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | 7.9 | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | 8.05 | | <1.000 |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | 8.08 | | <1.000 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | 7.57 | | <1.000 |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | 7.33 | | <1.000 |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | | 0.0139 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | 7.4 | | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | 7.43 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | 7.3 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | 7.1 | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | 7 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | 7.3 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | 7.4 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | 7.2 | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | TDS (mg/L) | TSS (mg/L) | Total Organic Carbon (mg/L) |
|--------------------------------------|---|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|------------|------------|-----------------------------|
| Primary Maximum Contaminant Levels | a | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | b | | | | | | | | | 500 | | |
| Recommended Action Levels | c | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | 168 | 18.8 | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | 140 | <2 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | 132 | 8.5 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | 170 | <2 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | 112 | <2 | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | 160 | <2.000 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | 164 | 2 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | 140 | <2.000 | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | 145 | <2.000 | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | 220 | <2.000 | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | 196 | <2.000 | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | 130 | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | 198 | | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | 216 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | 218 | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | 194 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | 214 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | 228 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | 248 | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Oil & Grease (mg/L) | Hexane Extractable Material (mg/L) | TPH (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|---------------------|------------------------------------|------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | <5.000 | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | <0.100 |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | <0.100 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | <0.100 |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | <0.100 |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | | NON DETECT | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | | | <4.6 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Ex. 6 - Personal Privacy

Water Supply Lat/Long:41.747453/-75.881937

Water Supply Depth:UNKNOWN

Treatment (Y/N):N

Gas Well Operator:

Gas Well:BAKER R. 1V/3H

Distance:1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Total Coliform (cfu/ 100 mL) | Fecal Coliform (cfu/ 100 mL) | Aluminum (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|------------------------------|------------------------------|-----------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | 0 | 0 | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | 0.05-0.2 |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | <1 | <1 | 0.626 |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | 7 | 7 | <0.05 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | <1 | <1 | <0.05 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | <1 | <1 | <0.1 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | <1 | <1 | <.05 |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | <1.000 | <1.000 | <0.100 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | <1 | <1 | <0.05 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | <0.100 |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | <0.100 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | <0.100 |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | <0.100 |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | | | 0.301 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | <0.2 |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | <0.2 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | <0.2 |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | <1 | | <0.03 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | <0.2 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | <0.2 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | <0.2 |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Arsenic (mg/L) | Barium (mg/L) | Beryllium (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|----------------|---------------|------------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | 0.01 | 2 | 0.004 |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | 0.261 | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | 0.15 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | 0.14 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | 0.155 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | 0.136 | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | 0.146 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | 0.158 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | 0.162 | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | 0.162 | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | 0.269 | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | 0.269 | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | 0.0031 | 0.29 | 0.000089 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | 0.123 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | 0.119 | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | <0.001 | 0.115 | <0.001 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | 0.197 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | 0.146 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | 0.145 | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Ex. 6 - Personal Privacy

Land Owner:
Water Supply Lat/Long: 41.747453/-75.881937
Water Supply Depth: UNKNOWN
Treatment (Y/N): N
Gas Well Operator:
Gas Well: BAKER R. 1V/3H
Distance: 1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Boron (mg/L) | Cadmium (mg/L) | Calcium (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|--------------|----------------|----------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | 0.005 | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | NON DETECT | 0.00065 | 38.6 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | 36.8 |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | 40.1 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | 40 |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | 0.0092 | <0.001 | 36.1 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | 42.4 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | 40.8 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | 40.5 |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Chromium (mg/L) | Cobalt (mg/L) | Copper (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|-----------------|---------------|---------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | 0.1 | | 1.3 |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | NON DETECT | 0.0013 | 0.0247 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | 0.0036 | <0.0002 | 0.0061 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Iron (mg/L) | Lead (mg/L) | Lithium (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|-------------|-------------|----------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | 0.015 | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | 0.3 | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | 2.68 | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | <0.025 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | <0.025 | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | <0.025 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | <0.025 | | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | <0.025 | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | <0.05 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | <0.050 | | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | <0.050 | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | <0.050 | | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | <0.050 | | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | 0.15 | 0.0119 | 0.0139 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | 0.423 | | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | 0.183 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | 0.133 | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | 0.0928 | 0.0012 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | 0.429 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | 0.389 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | 0.354 | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Ex. 6 - Personal Privacy

Land Owner:
Water Supply Lat/Long: 41.747453/-75.881937
Water Supply Depth: UNKNOWN
Treatment (Y/N): N
Gas Well Operator:
Gas Well: BAKER R. 1V/3H
Distance: 1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Magnesium (mg/L) | Manganese (mg/L) | Silicon (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|------------------|------------------|----------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | 0.05 | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | 9.22 | 0.689 | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | 7.39 | <0.025 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | 7.47 | <0.025 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | 7.8 | <0.025 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | 7.17 | <.025 | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | 7.38 | <0.025 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | 7.61 | 0.041 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | 7.93 | <0.025 | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | 7.93 | <0.025 | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | 6.72 | <0.025 | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | 6.43 | <0.025 | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | 7.9 | 1.36 | 5.35 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | 8.233 | 0.216 | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | 8.375 | 0.084 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | 8.183 | 0.064 | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | 6.97 | 0.0689 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | 9.13 | 0.37 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | 8.313 | 0.214 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | 8.369 | 0.199 | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Mercury (mg/L) | Nickel (mg/L) | Potassium (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|----------------|---------------|------------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | 0.002 | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | NON DETECT | 0.003 | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | 1.006 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | 1.058 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | <1 |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | <0.0002 | <0.00025 | 0.916 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | 1.187 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | 1.055 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | 1.054 |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Silver (mg/L) | Sodium (mg/L) | Strontium (mg/L) |
|--------------------------------------|---|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|---------------|---------------|------------------|
| Primary Maximum Contaminant Levels | a | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | b | | | | | | | | | 0.1 | | |
| Recommended Action Levels | c | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | 0.27 |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | 0.206 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | 0.211 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | 0.21 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | 0.182 |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | | 0.197 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | 0.212 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | 0.186 |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | 0.188 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | 0.213 |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | 0.217 |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | NON DETECT | 8.6 | 0.15 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | 11 | 126 |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | 11 | 0.116 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | 10.7 | 0.109 |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | <0.001 | 9.43 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | 12.2 | 0.156 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | 11.6 | 0.125 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | 11.4 | 0.121 |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Ex. 6 - Personal Privacy

Water Supply Lat/Long:41.747453/-75.881937

Water Supply Depth:UNKNOWN

Treatment (Y/N):N

Gas Well Operator:

Gas Well:BAKER R. 1V/3H

Distance:1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Zinc (mg/L) | Thorium 228 (pCi/L) | Thorium 230 (pCi/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|-------------|---------------------|---------------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | 5 | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | 0.0648 | 0.15 | 0.035 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | 0.0423 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Thorium 232 (pCi/L) | Uranium 234 (pCi/L) | Uranium 235/236 (pCi/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|---------------------|---------------------|-------------------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | -0.004 | 0.47 | 0.027 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Uranium 238 (pCi/L) | Benzene (mg/L) | Ethylbenzene (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|---------------------|----------------|---------------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | 0.005 | 0.7 |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | <0.0005 | <0.0005 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | 0.42 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | | <0.001 | <0.001 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | MTBE (mg/L) | Toluene (mg/L) | m,p-Xylenes (mg/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|-------------|----------------|--------------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | 1 | 10 |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | <0.0005 | <0.0005 | <0.001 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | <0.001 | <0.001 | <0.002 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Ex. 6 - Personal Privacy

Land Owner:
Water Supply Lat/Long: 41.747453/-75.881937
Water Supply Depth: UNKNOWN
Treatment (Y/N): N
Gas Well Operator:
Gas Well: BAKER R. 1V/3H
Distance: 1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | o-Xylene (mg/L) | Acetylene (ug/L) | Ethane (ug/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|-----------------|------------------|---------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | 10 | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | 86.1 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | | 340 |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | 502 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | 567 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | | 180 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | 215 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | | 44 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | | 210 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | 131 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | | 110 |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | <0.0005 | | 37 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | | 200 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | 416 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | 410 |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | | 400 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | <0.025 |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | | <0.025 |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | | NON DETECT | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | | 12.6 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | | 17.4 |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | <0.001 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | | NON DETECT |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | <26 |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|-----|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | <26 |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|-----|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:

Water Supply Lat/Long:

Water Supply Depth:

Treatment (Y/N):

Gas Well Operator:

Gas Well:

Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937

UNKNOWN

N

BAKER R. 1V/3H

1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Ethene (ug/L) | iso-Butane (ug/L) | Methane (ug/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|---------------|-------------------|----------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | | 28,000 |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | | 4010 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | | 0.36 | 8200 |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | | 12300 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | | 15500 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | | 0.083 | 6500 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | | 5880 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | | 0.083 | 2200 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | | <0.05 | 6600 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | | 4580 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | | <0.05 | 5100 |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | | <0.050 | 4200 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | | <0.05 | 5200 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | | 10300 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | <0.050 | 10000 |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | | <0.050 | 9700 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | <0.050 | 0.47 |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | | <0.050 | 0.69 |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | NON DETECT | | ND (<0.5) |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | NON DETECT | | 491 |
| | | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | NON DETECT | | 1080 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | NON DETECT | | 2020 |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | NON DETECT | | 457 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | NON DETECT | | 170 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | NON DETECT | | 22.2 |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | | 457 |

| | | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|-----|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | | 402 |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|--|-----|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Ex. 6 - Personal Privacy

Land Owner:
Water Supply Lat/Long: 41.747453/-75.881937
Water Supply Depth: UNKNOWN
Treatment (Y/N): N
Gas Well Operator:
Gas Well: BAKER R. 1V/3H
Distance: 1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | n-Butane (ug/L) | Propane (ug/L) |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|-----------------|----------------|
| Primary Maximum Contaminant Levels | | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | 0.67 | 14 |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | 0.08 | 3.2 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | 0.26 | 0.7 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | 0.062 | 2.7 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | <0.05 | 0.71 |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | <0.050 | 0.087 |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | <0.05 | 1.7 |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | | NON DETECT |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | 0.051 | 3.9 |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | 0.054 | 3.5 |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | <0.050 | <0.050 |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | <0.050 | <0.050 |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | | NON DETECT |
| | | | | | | | | | | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | | NON DETECT |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | | NON DETECT |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | | NON DETECT |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | | <34 |

| | | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|-----|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | | <34 |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|-----|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)

Land Owner:
Water Supply Lat/Long:
Water Supply Depth:
Treatment (Y/N):
Gas Well Operator:
Gas Well:
Distance:

Ex. 6 - Personal Privacy

41.747453/-75.881937
UNKNOWN
N

BAKER R. 1V/3H
1250 FT

| | | | Sample Location | Sample Medium | Latitude | Longitude | Treatment Collection | Source | Sample Date | Sample Sheet Comments |
|--------------------------------------|--|--|------------------------------|---------------|-----------|------------|----------------------|--------------|-------------|---|
| Primary Maximum Contaminant Levels | | | | | | | | | | |
| Secondary Maximum Contaminant Levels | | | | | | | | | | |
| Recommended Action Levels | | | | | | | | | | |
| PRESSURE TANK IN WELL PIT | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 1/5/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 1/22/2009 | |
| SPIGOT AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | DEP | 2/3/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 3/26/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 4/14/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 4/30/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 5/13/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 6/14/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 6/30/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2009 | |
| BATHROOM TUB | | | Bathroom | Well | 41.747461 | -75.881937 | | CABOT | 8/13/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | CABOT | 9/21/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2009 | |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | * READINGS TAKEN OVER A BOTTLE FILLED WITH SAMPLE ` |
| PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 10/22/2009 | * READING TAKEN OVER A BOTTLE FILLED WITH SAMPLE ` |
| KITCHEN SINK | | | Kitchen Sink | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | |
| IN SHED AT PRESSURE TANK | | | Pressure Tank | Well | 41.747461 | -75.881937 | | CABOT | 11/9/2009 | |
| | | | | Well | 41.747461 | -75.881937 | | TEST AMERICA | 1/21/2010 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/16/2010 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 9/23/2010 | SAMPLE WAS TAKEN FROM 550 GALLON TANK. THIS TANK WAS NOT COVERED WITH TARPS LIKE THE OTHER TWO IT IS JOINED TO. LEL READING WAS FROM DRILLED WELL, WATER WAS BEING RUN WHEN LEL READING WAS TAKEN |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 10/21/2010 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/3/2010 | |
| WELL (FORMER DRINKING WATER) | | | Well (Former Drinking Water) | Well | 41.747461 | -75.881937 | | K&L | 11/8/2010 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 11/23/2010 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/2/2010 | |
| | | | | Well | 41.747461 | -75.881937 | | DEP | 12/8/2010 | |
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 7/20/2011 | |

| | | | | | | | | | | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|
| WELL 1 | | | Well | Well | 41.747461 | -75.881937 | | CABOT | 8/9/2011 | |
|--------|--|--|------|------|-----------|------------|--|-------|----------|--|

Notes:
a - Maximum Contaminant Levels per E.P.A.'s National Primary Drinking Water Regulations. Safe Drinking Water Act (42 USC Chapter 6A Section 300f)
b - E.P.A. National Secondary Drinking Water Regulations are non-enforceable guidelines regarding contaminants that may cause cosmetic effects or aesthetic effects in drinking water.
c - Recommended action level from the Office of Surface Mining Reclamation and Enforcement - Appalachian Regional Coordinating Center, Pittsburgh, PA (September 2001)